



LEYENDA

Con bomba inoxidable	
X11	Borne principal Bornier principal Mains terminals
SW21	Interruptor de seguridad Switch sécurité Safety switch
R1-6	Resistencias Corps de chauffe Heating element
K21	Relé de resistencias Relais chauffage Relay heating elements
K11	Relé de seguridad Relais sécurité Relay safety
S1/S2	Sonda tipo K (Termostato de trabajo y seguridad) Sonde type K (Thermostat de travail et de séc.) Probe type K (Control-and safety thermostat)
E - F	Terminales control energia Bornier système controle d'énergie Energie control terminals
SW22	Contacto potencial libre Contact avec potentiel libre Free potential contact
F10	Termostato de seguridad Thermostat de sécurité bi-métal Safety thermostat

Tipo	3NAC400V 50/60Hz 3L+N+PE	NOTAS / REMARQUES / NOTES
		Máquina con dos líneas Machine with 2 supply line
FFS42 / FFS42 - E	5x2.5mm²	Machine avec 2 câbles d'alimentation
		FFS 42 -E = solo 1 bomba
		FFS 42 -E = only 1 pump command
		FFS 42 -E = 1 seule commande pompe

	Esquema eléctrico Elektroschema Electrical Diagram	Standard FFS 42		Válido desde:		frifri aro s.a.				
		FFS 42	2x7.5 kW	No.de aparato:		2520 La Neuveville		Fecha	Visa	No. Esquema
				No. Serie		15/02/00	OB	500528		d
				Fecha	11/12/98					
				Visa	OB					